	LOCKHEED AIRCRAFT CORP.			CHANGE PROPOSAL X					
DATE	20 SEPTEMBE	AFF	ECTS:	WSP	° []	PR	OJECT []	 ]	
NAME	OF MAJOR COMP	PONENT	PART OR LO	WEST SUB	ASSEMBLY	; F	ART NO. 8	MODEL (	OR TY
TITLE	OF PROPOSAL:	syst	. 15 ANTEN	NA ISOLAT	TON IMP	ROVEMENT	1		<u> </u>
NATU	RE OF PROPOSAL:						W214		
		SEE I	PAGE 2						
				•					
					•				
REASO	ON FOR PROPOSAL	<u>.</u>		· · · · · · · · · · · · · · · · · · ·	•			<u> </u>	<del></del>
	•								
		SEE PA	GE 2						
<u> </u>									
			$\infty$						
		•						·	
									٠.
ES	ESTIMATED COST	AND TIME I	NVOLVED :						
	ADDITIONAL FUNE			·					
CP	ESTIMATED COST		L	None	<b>SP-1</b> 922				;
	ADDITIONAL FUND		KEU ;	HOHE	or=1922			<del> </del>	<del></del>
ITEMS	AFFECTED BY PRO	POSAL:	<u> </u>						·
SAFETY	MISSION PERFO EFFEC- AN TIVENESS	ORM- OPERATII CE PROCEDU	NG INTER- CHANGE- ABILITY	WEIGHT OR WEIGHT & BALANCE	TOOLS & SUPPORT EQUIPMENT	MAINTE- NANCE PROCEDURE	SERVICE LIFE	FLIGHT MANUAL	MAII NAN MAN
	X C								
EST, N	AN/HRS. REQ'D. TO	O ACCOMPL	ISH CHANG	E IN FIELD				M	·
SOURC	CE OF PARTS FOR I	KIT		AVA	ILABILITY	, 9	WEEKS AF	TER APPRO	IVAL
DISPO	SITION OF SPARES	AFFECTED	Concun:	00/054					
	NONE			EDD /OSA					

LAC ECP-167 Page 2 of 2

## NATURE OF PROPOSAL:

AN-W75 absorbent material will be installed on the inner surface of the System 15 radome between the antennas. 17 Pieces, 2.50 in. x 12.75 in., will be installed between the beads of the radome. One piece, 7.50 in. x 11.00 in., will be installed on the access door. The absorbent is 1 3/8 inch thick, self extinguishing, and weatherproofed with a neoprene coated nylon fabric. The absorbent complies with MIL-C-20696 and has a cut off point of 2.0 GC.

The absorbent will be bonded to the radome surface with a compatable cement recommended by the absorbent manufacturer.

Tests by the manufacturer of System 15 show that this type of installation will provide 70 db, or better, attenuation between antennas.

## REASON FOR PROPOSAL:

System 15 was designed to operate with a minimum antenna isolation of 70 db. Tests conducted by the manufacturer of System 15 indicate that this isolation is not attained in the present System 15 installation. These tests also showed that AN-W75 absorbent material will provide the proper antenna isolation.

It is the Contractor's understanding that the manufacturer of System 15 is negotiating modifications to the system which will allow satisfactory operation with a minimum antenna isolation of 50 bd.

These modifications and the changes listed above will provide a "safety factor" of 20 db between the isolation provided and the isolation required for satisfactory operation.

Prepare and issue Service Bulletin Kits.